PRINCE GEORGE'S COUNTY HISTORIC SITE SUMMARY SHEET

Survey #: P	.G. #87A-25	Building Date:	1901	
Building Name	: _Vine Cottage			
Location: 1	7401 Milltown Landin	g Road		

Private/Residence/Occupied/Fair/Inaccessible

Description

Vine Cottage is a two-story frame dwelling of two-by-two-bays with a twostory, two-by-one-bay frame kitchen wing. Located just south of Milltown Landing Road, it is surrounded by open fields. The two-bay north gable end has entrance in the second bay through a door with twelve upper glass lights and a lower, horizontal wood panel. Windows are 1/1 with louvered shutters. A three-bay entrance porch wraps around the northwest corner of the building and across the west facade. The porch roof is supported by turned and chamfered posts. The building has horizontal wood siding and rests on a brick foundation. The crown molded, boxed cornice is returned in the gable ends. The pediments in the north and west gable ends are sided with fishscale shingles. The two-bay west facade has a two-story, gable roof projecting bay with the same pediment treatment as the north gable end. The south gable end is dominated by the gable roof kitchen wing on the southwest corner. The wing is contemporary with the main block. The complex of outbuildings east and south of Vine Cottage includes a two-story gable roof barn/stable which predates the house. A large tobacco barn and a one-by-one-bay frame gable roof meat house are contemporary with the house. Close to the road is a two-story, two-by-onebay shop building of vertical wood siding. The building contains a line drive from which several types of farm or woodworking equipment were run simultaneously. East of the house is a one-story, one-by-one-bay gable roof frame generator house and south of the house is a terraced garden.

Significance:

Vine Cottage was built in 1901 by James Burns Wilson, in the vicinity of an earlier Wilson house. The 59.7 acre property was a part of four parcels totaling 655 acres acquired by James Wilson in 1739. The Wilson family has held a part of this property to the present time. Vine Cottage is a fine example of a late 19th/early 20th century farmhouse in Prince George's County. Stylistic elements include its two-story height, wrap-around porch with turned posts, gable end entrance displaying prominent cornice returns and decorative shingle. The dwelling is part of a complex of agricultural buildings built during the early 20th century. These include a 1-1/2 story 1 x 1 frame structure built during the 1920's to house a generator. There is also a two-story shop building. Vine Cottage is one of three Wilson family dwellings in the vicinity. They are local landmarks due to architectural style and association with one family. Vine Cottage is also significant for its complex of farm buildings.

Acreage: 59.7 acres

Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

Magi No.

1. Nan	1e (indicate p	referred name)		
historic Vine	Cottage			
and/or common				
2. Loca	ation			
street & number	17401 Milltown L	anding Rd.	_	not for publication
city, town	Aquasco	vicinity of	congressional district	4
state Md.		county	Prince George's Co	ountv
3. Clas	sification			
Category district (building(s) structure site object	Ownership public private both Public Acquisition in process being considered X not applicable	Status _X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted _X no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresses	of <u>all</u> owners)
name Robert	B. and Patricia I	. Wilson		
street & number	17401 Milltown L	anding Rd.	telephone no	.:
city, town Bra	ındywine	state	and zip code Md	20613
5. Loca	ation of Leg	al Description		20010
		ce George's County C	ourthouse	liber 5877
street & number	Main Street			folio 263
city, town Upp	er Marlboro		state	Md.
6. Repi	resentation	in Existing	Historical Surve	eys
title N.A	•			
d ate			federal state	county local
depository for su	ırvey records			
city, town			state	
				

7. Description

Survey No 4(-87A-25

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Vine Cottage is a two-story frame dwelling of two-by-two-bays with a two-story, two-by-one-bay frame kitchen wing. It is located just south of and fronting on Milltown Landing Road, and is surrounded by open fields.

The two-bay north (main facade) gable end has entrance in the second bay through a door with twelve upper glass lights and a lower, horizontal wood panel. Windows on the facade are 1/1 double-hung-sash with wooden louvered shutters. A three-bay hipped roof entrance porch wraps around the northwest corner of the building and continues across the west facade. The porch roof is supported by turned and chamfered wood posts. There is a wide plain frieze below the porch cornice.

The building is sided with horizontal wood siding painted white and rests on a brick foundation. The crown molded, boxed cornice is returned in the gable ends. A wide plain siding board runs around the building below the cornice, forming a frieze and creating pedimented gable ends. The pediments in the north and west gable ends are sided with fishscale shingles.

The two-bay west facade has a two-story, gable roof projecting bay on the southwest corner of the main block. It has the same pediment treatment as the north gable end. There is an entrance on the north side of the projecting bay, sheltered by the west three bays of the ell-shaped entrance porch.

The south (rear) gable end is dominated by the gable roof kitchen wing on the southwest corner. The wing is of the same materials and is contemporary with the main block. Windows are 6/6 double-hung-sash. The south gable end of the wing is unfenestrated and has an interior corbelled brick chimney at the gable peak. There is a shed roof screened porch on its west side, sheltering a central entrance with a four panel door.

There is a complex of outbuildings east and south of Vine Cottage. A small, two-story gable roof barn/stable with vertical wood siding and standing seam metal roof predates the house. A large gable roof tobacco barn resting on brick piers, and a one-by-one-bay frame gable roof meat house are contemporary with the house. Northeast of the house, close to the road, is a two-story, two-by-one-bay shop building with vertical wood siding, a gable roof and central double entrance doors facing south. The building contains a line drive suspended at head level along the south wall. Several types of farm or woodworking equipment were run simultaneously using this piece of equipment. There are also various antique hand tools in the building. The shop building is also contemporary with the

8. S	ign	ificance		Survey No.PG-87A	-25
Period	-1499 -1599 -1699 -1799 -1899	Areas of Significance—C archeology-prehistoric archeology-historicX agricultureX architecture art commerce communications	community planning conservation economics education engineering	law literature military music ent mostor politics/government	science sculpture social/ humanitarian theater transportation
1900 communications industry politics/government transp					
check:	ar Appli	nd/or icable Exception:	ABCD		
support	of a acre Tren Wils	Vine Cottage was buin earlier Wilson hous property was origina ant and Good Luck, to on in 1739. ² The Wilerty through to the p	It in 1901 by James se which was torn do ally a part of four otaling 655 acres, w son family has held oresent time. ³		e vicinity ne 59.7 Dunbar, James f this
	elem gable tive ings stor to he is a cont	ury vernacular farmho ents include its two- e end entrance displa shingle. The dwelli built during the ear y-and-one-half, one-b ouse a generator for lso a two-story shop ains early twentieth	ouse built in Prince story height, wrapory against the correct of a correct throughout the contact of the correct of the corre	e George's County. Second porch with turnice returns and use complex of agriculturary. Outbuildings incorructure built during the farm. The farm with the house, we mechanical equipment.	tylistic rned posts, of decora- al build- lude a the 1920's There which There
	Road one	nity. The dwellings, , are local landmarks	within eyesight of due to architecture is also significar	Wilson family dwelling feach other on Millton all to the contract of the complex of the complex of	on Landing tion with
	Note	<u>s</u>			
	1 C	onversation with Edna	Connick Wilson, Ap	oril 1985.	
	2 L	and Records of Prince	George's County, Y	7:100 .	

 3 Land Records of Prince George's County, JRM 9:179; and Wills, Docket 1810, Josiah Wilson and David B. Wilson; William James Wilson, Administration #651.

4 Conversation with Mary E. Wilson, January 1986.

See notes, #8

<u>10. Ge</u>	ograpinoar Data			
	inated property 59.7 acres		map 175	parcel 7
Quadrangle nan	ne Lower Marlboro H		Quadran	gle scale
UTM References	do NOT complete UTM referen	nces		÷
Zone Easti	ing Northing	B Zone	Easting	Northing
c		▫┕╻┪		
E		F		
$G \sqcup J \sqcup \bot$		н []		
	ary description and justification			
List all states	and counties for properties overlag	pping state or cou	unty boundarie	s code
	and counties for properties overla		unty boundarie	
state	and counties for properties overlage	county	unty boundarie	code
state state 11. Fol	and counties for properties overlaged code	county	unty boundarie	code
state	and counties for properties overlage code code	county county Historian		code
state state 11. Foli	and counties for properties overlag code code rm Prepared By Marina King, Architectural Historic Preservation Commi	county county Historian ssion dat		code code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

#7. Continued

house. There was a small saw mill west of the shop building which has recently been demolished. Directly east of the house is a one-story, one-by-one-bay gable roof frame generator house on a high cement foundation. This building was built during the 1920's and housed a generator which provided electricity for the house.

South of the house is a terraced garden. The garden terraces and a decorative pond west of the house were formed using the distinctive fossilized oyster shell rock found in this area.

The interior of Vine Cottage has door and window surrounds of banded wood molding with bullseye corner blocks. The molding is varnished rather than painted.

Chain of Title

Vine Cottage P.G. #87A-25

5877:263 10 April 1984 Deed


Mary E. Wilson to Robert B. and Patricia I. Wilson and Clifford A. and Roberta W. Jenkins. For \$125,000 grantor conveys tract in Aquasco of 59.7 acres. Same land described in deed from Odell C. Rawlings to Ellen Wilson and Mary E. Wilson, 1106:178, 3-11-1949.


1106:178 19 Feb. 1949 Deed Odell C. Rawlings to Ellen Wilson and Mary E. Wilson. For \$10.00 grantor conveys that land obtained from William Burns Wilson, 19th February 1949 recorded prior hereto. Tract 59.7 acres.


1106:176 19 Feb. 1949 Deed William B. and Ruth E. Wilson, Kenneth G. and Edna C. Wilson, Bessie and Bertram Kalisch, Ellen Wilson and Mary E. Wilson to Odell Rawlings. Esther Wilson died intestate 1947, leaving brothers and sisters as heirs. She died possessed of one-third interest in property obtained from James B. Wilson and Henrietta Wilson, 16 Feb. 1934, 417:82. 59.7 acres.

417:82 16 Feb. 1934 Deed James B. Wilson and Henrietta Wilson convey to Ellen Wilson, Esther Wilson and Mary E. Wilon that parcel containing 59.7 acres. Same conveyed to James B. Wilson by deed of partition from William Walter Wilson and Emma G. Wilson, 21 Aug. 1886, JWB: 38:203.

JWB 38:205 21 Aug. 1886 Deed William Walter Wilson and Emma G. Wilson to James Burnes Wilson. Both then tenants in common of property inherited from parents, William James Wilson and Margaret Johns Wilson. Decide on a division of equal worth. James B. Wilson allotted eastern parcel, contains 96.20 acres, Lot 2 of this division. Same land inherited by William James Wilson from his father David B. Wilson. Dunbar, Tenant and Good Luck, purchased by James Wilson from Thomas Sheredive by deed dated October 30, 1739, Liber Y:100 and partitined among his heirs in JRM 9:179.









P.G.#87A-25


Vine Cottage Prince George's County, MD

Marina King

January 1986

Generator, meat house, north elevation

Neg: Md. Hist. Trust, Annapolis, MD



P.G. #87A-25

Vine Cottage
Prince George's County, MD.
Marina King
January 1986
Workshop, south elevation

Neg: Md. Hist. Trust, Annapolis, MD.



P.G.#87A-25

Vine Cottage Prince George's County, MD Marina King

Jan 1986

8

North facade Neg: MD Hist. Trust, Annapolis, MD



Vine Cottage Prince George's County, MD Marina King January 1986 East elevation Neg: Md. Hist. Trust, Annapolis, MD

P.G.#87A-25



P.G.#87A-25

Vine Cottage Prince George's County, MD Marina King Jan 1986

West facade

Neg: MD Hist Trust, Annapolis, MD





Vine Cottage

Marina King Jan 1986

Southeast facade

Prince George's County, MD

Neg: MD Hist. Trust, Annapolis, MD

P.G.#87A-25